ORIGINAL JOHNSON UTILITIES COMPAN

0000021255

51

5230 East Sha Bouleurd * Scottabale, Arizona 85254 PH: (490) 998-3300; FAX: (490) 483-7908

June 9, 2005

Brian Bozzo, Compliance Manager Utilities Division Arizona Corporation Commission 1200 W. Washington Street Phoenix, Arizona 85007 Arizona Corporation Commission

DOCKETED

JUN - 9 2005

DOCKETED BY

RE:

Johnson Utilities Company: Compliance with Decision No. 65840, 64062

Annual Wastewater Compliance with ADEQ regulations

ACC Docket Nos.: WS-02987A-99-0583; WS-02987A-00-0618; W-02234A-00-0371;

W-02859A-00-0774; W-01395A-00-0784

Dear Mr. Bozzo:

Please accept this letter as a follow-up to my May 20, 2005, letter to you concerning the above captioned matter. Enclosed please find the Arizona Department of Environmental Quality's (ADEQ) Letter of Compliance for Pecan Ranch WRP indicating the facility is in compliance attached hereto as Attachment No. 1.

Johnson Utilities is still working diligently with ADEQ to obtain the wastewater compliance status report letter for the Section 11 WRP. Johnson will file the final compliance letter as soon as it is issued by ADEQ. Should you have any questions, please do not hesitate to contact me. Thank you for your time and consideration in this matter.

Since felv.

Daniel Hodges

Johnson Utilities, LLC

Enclosure

Cc:

Brian Tompsett, Johnson Utilities (w/out enc.)

Ernest Johnson, Director- (w/enc.)

Docket Control (w/enc.)

AZ CORP COMMISSION

ATTACHMENT 1



ARIZONA DEPARTMENT OF ENVIRONMENTAL QUALITY



1110 West Washington Street • Phoenix, Arizona 85007 (602) 771-2300 • www.adeq.state.az.us

May 25, 2005

Johnson Utilities Company Mr. Brian Tompsett, Vice President 5230 E. Shea Blvd, Suit 200 Scottsdale, AZ 85254

RE: Compliance Status for Pecan Water Reclamation, Inventory number P-105324,

Place Id: 18583, Permit number: 29510.

Dear Mr. Tompsett;

Your request for evaluation of compliance status for the above facility is completed. Our records indicate that Pecan Water Reclamation has Aquifer Protection Permit number 29510 issued on May 7, 2004.

The Aquifer Protection Permit reporting requirements and monitoring results which have been submitted indicate the facility is in compliance based on the current information that is available to ADEQ and no enforcement actions are pending.

It should be understood that the compliance status of a facility may change from time to time based upon monitoring results or a facility inspection. Therefore this is based on the most current information available.

Sincerely,

Fred Vakili, EHS II

Water Quality Data Unit

Water Quality Compliance Section

Northern Regional Office 1515 East Cedar Avenue • Suite F • Flagstaff, AZ 86004 (928) 779-0313 Southern Regional Office 400 West Congress Street • Suite 433 • Tucson, AZ 85701 (520) 628-6733

Printed on recycled paper